

# Brother ScanNCut Tutorial: Fixing Problems with Welding Text in ScanNCut Canvas

With Brother's introduction of the Type Converter, it now makes it possible to use pretty much any font with your ScanNCut machine. However, not all fonts are created equal and you may find that when you try to start welding fonts in ScanNCut Canvas that you may get all sorts of issues. One of the most common is the error message `ErrS07 – [Cannot execute this operation with an open or intersecting path. (ErrS07)]`

So when a reader asked us to take a look at a font she was having trouble with, we felt a video tutorial was in order to try to explain the process we go through when we see this message and also how to weld text without losing the inside shapes of those letters like O and B for example.

**Watch the Video below:**